Abstract of the Disclosure

Developer roller (5) is rotated rapidly for high speed printing, which can cause excessive heating at end seal (1). Heat damage to toner (24) is avoided by providing gaps (30a, 30b) under the seals (1) which reduce the stiffness of roller (5) and thereby reduce frictional heating.